Computer Readable Safety Observation Report Cards:

Manual vs. Scanned Reporting for 100 SOR cards:

Manually (between 2 - 4 hours):

Manually entering one SOR card will take approximately 2 minutes per card. Therefore, manually entering 100 cards can take anywhere between 2 and 4 hours depending on the skill set of the employee and the number of interruptions.

It is common that the person entering the card is not always the person correcting the issue. This means that the SOR card potentially goes through more hands than necessary. If it is not the same person solving the issue (for example, a safety professional vs. an administrative employee who is not in the field), he or she would have to read and grade every card again before entering.

In addition, a bilingual card makes this process more complicated. It assumes that a person is bilingual, and if he or she it not, it requires time from a 2^{nd} employee. In short, it can be both time-consuming and prone to inaccuracies in reporting.

Scanned (about 15 minutes):

It takes the scanner about 2 seconds to scan a card and between 3-6 seconds for the computer to process each card depending of the speed of the computer. The scanner can scan and process 100 SOR cards in 5 -7 minutes depending on the speed the computer. Once entered, the employee takes about 5 minutes to correct possible scanning errors and to copy and paste the exported data into the Excel spreadsheet. Possible scanning errors can be prevented by educating safety professionals to fill out the card properly. The spreadsheet will do all the necessary calculations in order to show the desired result.

The new card has greatly improved the time it takes to get information from the SOR card back to reporting a potential problem. Consistency is important when it comes to reporting. The safety professional is closer to the issue and therefore is also the best qualified to report a potential safety problem. The new card is easily graded by the safety professional with 5 checkmarks after he or she has corrected the issue. Redesigning the SOR card and making it readable by a computer has greatly decreased the number of errors. Most important of all, the data will be available for use in future reporting.

AUTOMATED SAFETY OBSERVATION REPORT SCANNER

Front Back Merck Global Engineering Services Publication Location: Safe Observation Report Durham, NC, USA ID 34 264-345908 Safe Observation Report (Reporte de Observación de Seguridad) Please do not mark with This side is for Safety Managers only ticks, crosses or circles. SOR is not to be used to assign b lame. (SOR no sera usado para asignar culpa.) SEE something and DO something. (Only one mark in each category) Mark like this: $\circ \bullet \circ$ (VEA algo y HAGA algo.) Priority Level/Prioridad - please check one: (chequar una caja) Project: Written by: Written aganinst Warehouse 00 Low/Bajo Allen, Anthony Acousti 0 Acousti High/Alto Med/Mediano Info/Positive/Positivas OO Lab 0 Focus On: (Enfocar en) Armistead, R. 0 Advancetec \Box Advancetec 0 VBE Arnold, Gary All Contractors 0 All Contractors Recognition for Safe Acts/Conditions (Reconocimiento Para Actos/Condiciónes Seguros) SDI Ο 0 Allied Fire 0 Unsafe Acts/Conditions Requiring Correction (Actos Inseguros/Condiciónes Que Requiren Correción) Barrera, Rick Allied Fire 0 0 Site/CBT/No Loc. 0 Blasingame, Z. American Safety 0 American Safety Ο Observer's Name: (Optional) Boone, Dorian Bahnson 0 Bahnson (Nombre de Observador: (Opcional) Priority Level: 00 0 Brown, Alex Brand Insulation Brand Insulation Company: (Optional) High Medium Low Positive 00 Carson, John **BWB** Constructio 0 **BWB** Construction (Compañia: (Opciónal) 0 Observation Location: (Required) 0 Dvorak, Ota Cap. Drywali (CDI) 0 Cap. Drywall (CDI) 0 00 \mathbf{O} (Lugar de Observación (Requerido) 0 0 0 Goff, Jim Carolina M. (CMS) Carolina Mech(CMS Date/Time: (Required) 0 0 Gollings, Jamle Commercial insta 0 Commercial Install (Fecha/Hora: (Requerido) Company Identified: (Required) Corrective Observations: ammonds, F. Ο Cooper Cooper (Compañia Identificada: (Requerido) 0 Hinson, limmy Dante 0 Dante \bigcirc PPE Ο 0 Elia, Jim Dynamic Sys (DSI) 0 Dynamic Sys (DSI) Check all that app ly: 0 EQUIPMENT/VEHICLE USE Jay, Bill 0 0 Falman's 0 Eatman's Behavior (Comportamiento) Condition (Condición) Procedure (Proced imiento) LeBlanc, A. 0 Environamics 0 Environamics 0 SLIP/TRIP/FALL · Acts/Conditions Observed (Actos/Condiciónes Observadas): 00 Main, Darrin Environm. (EAS) 0 Environmental(EAS) SHARP EDGES/PINCH PIONTS/PROTRUDING ITEM O 00 McGlone, R Epoxy Sys 0 Epoxy Sys 0 TRENCHING/EXCAVATION 0 0 McChargue, R. Freedom Indust 0 Freedom Indust. Mercer, Sherry 0 0 Gamewell (GMI) 0 Gamewell (GMI) 0 FALL PROTECTION Morrissy, Brian Global 0 Global \Box FIRE PREVENTION 0 O'dell, Andy Hales 0 Hales \Box HEALTH HAZARDS • Immediate Action Taken (Acción Tomada Inmediatamente): Hamlin Roofing Poelma, Joe Hamlin Roofing 0 Riches, Jon 0 \bigcirc HOUSEKEEPING Hawkins 0 Hawkins Ο Robey, Alicia lacobs 0 Jacobs 0 ISA/PERMITS/INSPECTIONS Rohs, Carl lacobs FSNA 0 lacobs FSNA 0 LOCKOUT/TAGOUT 00 Sgrol, Steve Merck 0 Merck 0 MANUAL LIFTING Woods, Roy 00 Mike Ellington 0 Mike E. (MEGP) · Follow Up Action (Seguimiento Complementario): 00 Ziller, George RMR RMR 0 TOOLS/MATERIALS 0 Siemens Slemen \bigcirc RIGGING/HOISTING Southern Indust. 0 Southern Indust.(SIC SCAFOLDS/LADDERS/ 0 0 0 STAIRWAYS Unified 0 Unified 0 0 Unknown 0 Unknown 0 SIGN5/BARRICADES 0 ITT 0 UTT WELDING/CUTTING/GRIN Issue Status (Problema Está) : Closed/Concluido Op en/Abierto 0 DING 0 0 Vendor 0 Vendor Action Assigned To (Acción Asignada Por) : ELETRICAL 0 0 Vista/Comint 0 Vista/Comint Observer Notified of Corrective Action?/¿Se le notifico al observador sobre acción de corrección tomada? Yes/Si No 0 0 0 HAZCOM WST 0 WST *Please Complete Reverse Side* 00 Not listed \mathbf{O} Not listed 0 OTHER (*Por Favor Llenar al Otro Lado*)